

STS-113 PRE-LAUNCH PAD DEBRIS INSPECTION REPORT
KSC Debris Team
21 November 2002

The pre-launch inspection of the MLP-2, Pad A FSS and RSS was conducted on 21 November 2002 from 1430 to 1730 hrs EDT.

Three facility items were documented in Appendix K of S0007VL4.

- Extension cable left on -Y ET access platform.
- Debris (approximately 3-inches by 1/2-inch) in the first red water trough North of the LH SRB.
- Debris on MLP deck and in gutter around MLP zero level.

All items were in work at the conclusion of walkdown.

Overall the Launch Pad was in excellent condition.

No vehicle items were noted.

Armando Oliu
NASA-KSC